

2014 MITSUBISHI Delica D2 X		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
MB15S	1,242 cc		
YEAR / REG.	MILEAGE		
2014/04	50,000 km		
DOORS	SEATS		
5	5		
TRANSMISSION	FUEL		
AT	Petrol		
STEERING	EXTERIOR COLOR		
Right	Blue		
BODY TYPE			
Minivan			
CHASSIS NO.	DIMENSIONS (L X W X H)		
MB15S-252441	371 × 162 × 177 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, minor exterior scratches, water droplets inside grille.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H26 / 4月	メーカー 三菱	ドア枚数 5	ボディ形状 ミニバン/ワンボックス	評価点 4
車名 デリカD:2 X	グレード 2WD	駆動方式 4WD	内装 A・B・C	
車種 自家用・その他 ()	排気量 1200 CC	型式 MB15S	通称 型式	
燃料 ガソリン	ディーゼル	燃料 ハイブリッド ()	燃料 シフト	
走行 50,000 km	インパネ	AT	走行 50,000 km	
外装色 ブルー	カラーNo. ()	エアコン Qd・AAG・WAG・()	装備品のみ O印 を記入	
()	内装色 ()	乗車定員 5人	サンルーフ	革シート
左・右 左・右	ディーラー ディーラー	走行 11,180円	エアパック	ABS
セールスポイント				
CD/ETC横滑り防止装置 (ESC) /運転席エアバック /盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/フルセグTV /衝突被害軽減ブレーキ/衝突安全ボディ/オートクルーズコントロール/DVD再生				
検査記入欄				
内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ AA評価4点仕入れ グリル内部水滴				
修復歴 有・無				
A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 補修跡 S サイズ C 腐食 X 交換歴 YX 交換済				
登録No. 月 日 まで(名義できる方)				
車体番号 MB15S-252441				
FW (トビ) 傷A フレ 外装 小 (B・C) ホイル A・曲 A・フレ エアロ シリアル No.				
内装 (ゴ) シス ヤブレ コガ コガク オーディオ (D) 車輪 長さ cm 幅 cm 高さ cm 最大積載量 Kg				