

2014 MITSUBISHI ek Space 660 E		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-B11A	DISPLACEMENT 659 cc		
YEAR / REG. 2014/07	MILEAGE 57,000 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Silver		
BODY TYPE Hatchback			
CHASSIS NO. B11A-0018109	DIMENSIONS (L X W X H) 340 × 148 × 178 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Interior dirty, seat stains, steering wheel scuffs, left power mirror cracked, keyless remote broken, front lower support minor dent			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H26 / 7月	メーカー 三菱	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 3.5																				
車名 e Kスペース	グレード 660 E キーレス ペンチ\$ アイドリングストップ	駆動方式 2WD 4WD																						
車種 自家用 ・ その他 ()	排気量 660 CC	型式 DBA-B11A	通称 型式	内装 A ・ B																				
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	検出過剰品 (保証書 ・ 取扱説明書 等)																					
走行 57,000 km	シフト インパネ	CVT																						
外装色 クールシルバーメタリック	カラーNo. ()	エアコン Qb ・ AAG ・ WAG ・ ()	装備品のみ ORP を記入																					
()	内装色 ()	乗車定員 4 人	PS	AW																				
左 ・ 右	ディーラー ・ 運行	9,190円	エアロック	ナビ																				
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/アイドリングストップ/ベンチシート/CD/両側スライド																								
検査記入欄 室内汚れ シートシミ ハンドル握れ 左電格ミラー・ワレ キーレス破損 フロアサポートU		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>			A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	Q	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
		登録No. 月 日 までにも変更できる方																						
		車体番号 B11A-0018109																						
FW トピ石 傷A フレ 外装 小 A ・ U A ・ 曲 A ・ フレ		シリアル No.																						
内装 300 シ		車種 長さ cm 幅 cm 高さ cm 最大積載量 Kg																						