

2014 MITSUBISHI Galant Fortis SB Sports		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CX6A	DISPLACEMENT 1,798 cc		
YEAR / REG. 2014/07	MILEAGE 30,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Sedan		
CHASSIS NO. CX6A-0400214	DIMENSIONS (L X W X H) 459 × 176 × 152 cm		
SALES POINTS			
Alloy Wheels Back Camera		Cruise Control Navigation System	
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, exterior minor and light scratches, lower end panel distortion, rear bumper hose distortion.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H26 7月	メーカー 三菱	ドア枚数 5	ボディ形状 セダン	評価点 4
車名 ギャランフォルティススポーツバック	グレード スポーツ	駆動方式 2WD	4WD	
車種 自家用・その他	排気量 1800 cc	型式 CX6A	燃費 A・B・C	
車検 - 年 - 月 - 日	燃料 ガソリン	ディーゼル	後日課税品 (保証書・取扱説明書等)	
走行 30,000 km	フロア	AT		
外装色 ライトニングブルーマイカ	カラーNo. Qd・AAG・WAG・()	エアコン	新着品のみ O印 を記入	
内装色 ()	乗車定員 5人	サンルーフ	高シート	
小売 左・右 ディーラー・車行	12,400円	エアバック	ABS	EV
セールスポイント CD/バックカメラ/ESC/横滑り防止装置(ESC)/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/メモリーナビ他/フルセグTV/衝突安全ボディ/オートクルーズコントロール/DVD再生				
検査記入欄 内装キズ、汚れ シートスレ、シワ 外装キズ、擦キズ AA評価4点仕入れ エンドパネル下部歪み R/Cノブボース歪み				
修復歴 有・無 A キズ U ヘコみサレ B キズヘコみ P 色あせ・ボケ Q ガラスズレ W 腐蝕跡 S サビ C 腐食 X 交換品 XX 交換済 売却No. 月 日 までに希望できる方 車体番号 CX6A-0400214				
FW A1	シロ	フレ	小 A・曲	エアロ A・フレ
内装 A1	シロ	ヤブレ	コガ	オーディオ A1
長さ cm	幅 cm	高さ cm	最大積載量 kg	