


2014 Mitsubishi i-MiEV Kei X		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ZAA-HA4W	DISPLACEMENT 1 cc		
YEAR / REG. 2014	MILEAGE 23,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Electric	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Kei		
CHASSIS NO. HA4W-0000794	DIMENSIONS (L X W X H) 339 × 147 × 161 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Corner pole damaged. Left door mirror has approx. 7cm damage, and the left front door has a 3cm dent from a door punch. Resin parts are faded. Small scratches on side decals. Minor scratches and scuffs on interior resin parts due to use. Please note that issues related to preventative maintenance (consumables, etc.) or general deterioration are not covered.			

年式登録番号	メーカー	車名	ドア数	ボディ形式	排気量
H26 / — 月	三菱	アイミーブ	5	軽四	4
車種	自動車・その他 ()	排気量 1 CC	型式 ZAA-HA4W	運転 型式	内装 A ⑨・C
車検 — 年 — 月 / ③	燃料 ガソリン ハイブリッド	ディーゼル ⑤	費用等品名 (保証書・取扱説明書 等)		
走行 ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿	シフト CVT				
外装色 パールホワイト	カラーNo. ()	④B・AAG・WAG・()	装備品のみのO印を記入		
内装色 ()	内装色 (色番号)記入	乗車定員 人	PS	PW	AW
左・(要)ディーター・	走行 10,210 円・	リサイクル車	エアバック	ABS	TV
セールスポイント					
検査記入欄	修復歴 有・⑥				
コーポラール保証 左ドアミラーに7cmほどの破損がフロントドアに3cmほどのドアパンチによる凹み 軽傷/バツに自やけ サイドのデカールに小キズが3か所あり 内装面/バツに使用し小キズやスレキズ 当車庫に対する整備の要(消耗品等)の不具合、劣化等に関しては売買事項となります。	名義人 氏名 住所 〒 市 区 丁目 番 号 番 電話 FAX				
車検 番号	HA4W-0000794				
FW ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿	339 147 161				