

2014 Subaru Forester 2.0XT EyeSight 4WD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-SJG	DISPLACEMENT 1,998 cc		
YEAR / REG. 2014/12	MILEAGE 130,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE SUV		
CHASSIS NO. SJG-026286	DIMENSIONS (L X W X H) 460 × 180 × 174 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Adaptive Cruise Control Navigation System		Roof Rails Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Headlights fogged/hazy and dull, minor unevenness on right end panel, underbody rust, seat scuffs, carpet stains.			

年式登録番号	メーカー H26 / 12月	車名 スバル フォレスタ	ドアクラス 5	ボディ形式 SUV/クロカン	評価点 9																																																		
車種 自動車・その他（ ）	排気量 2000 cc	型式 DBA-SJ G	運転方式	内装 A・⑨・C																																																			
車検 - - 年 月 日	燃料 ガソリン	チャイセル ハイブリッド	後付部品品（保証書・取扱説明書等）																																																				
走行 [] [] [] [] [] [] [] [] [] []	シフト オート																																																						
変速機 フロア CVT																																																							
外装色 クリсталホワイト・パール（KIX）	カラーコード AG・WG・WAG・（ ）	新着品のみ O印 を記入																																																					
()	内装色 （ ）	乗員定数 5人	サンシェード																																																				
トランスミッション 左・(B) ディーゼル・前行	リサイクル料 13,010円	預託金 エプロン	革シート																																																				
セールズポイント																																																							
オートクルーズコントロール、バックモニター、HIDヘッドライト、純正メモリーナビ、TV、ETC、キーレス、スマートキー、社外アルミホイール、第三者機関鑑定済み																																																							
検査記入欄																																																							
ヘッドライト曇り・くすみ、Rエンドパネル小UA、下廻りサビ、シートずれ、カーペット汚れ																																																							
修正箇所 有。(B) <table border="1"> <thead> <tr> <th>A</th><th>キズ</th><th>U</th><th>ヘコみ凹み</th><th>B</th><th>キズへこみ</th><th>P</th><th>色あせ・汚れ</th><th>G</th><th>ガラスの欠け</th></tr> </thead> <tbody> <tr> <td>W</td><td>補修済</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr> <tr> <td>検査日</td><td colspan="8">月 日</td><td>名度中</td></tr> <tr> <td>車体番号</td><td colspan="9">SJG-026286</td></tr> <tr> <td>車検番号</td><td colspan="9">No.</td></tr> </tbody> </table>						A	キズ	U	ヘコみ凹み	B	キズへこみ	P	色あせ・汚れ	G	ガラスの欠け	W	補修済	S	サビ	C	腐食	X	交換済	XX	交換済	検査日	月 日								名度中	車体番号	SJG-026286									車検番号	No.								
A	キズ	U	ヘコみ凹み	B	キズへこみ	P	色あせ・汚れ	G	ガラスの欠け																																														
W	補修済	S	サビ	C	腐食	X	交換済	XX	交換済																																														
検査日	月 日								名度中																																														
車体番号	SJG-026286																																																						
車検番号	No.																																																						
FW	(B) (E)	ワレ	内装	小	カギル	エアロ	シリアル No.																																																
内装	(B) (E)	シミ	ヤブレ	コガ	コガサ	オデイオ	交換	傷	最大積載量																																														