

2014 Subaru WRX STI 2.0 STI		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-VAB	DISPLACEMENT 1,994 cc		
YEAR / REG. 2014/10	MILEAGE 37,549 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Sedan		
CHASSIS NO. VAB-003067	DIMENSIONS (L X W X H) 459 × 179 × 147 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Small wrinkles on seats, half leather seats, wheel scratches, various light scratches, body wrapping			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式番号	17722	車両区分番号	1001	シリアル番号		評価点	
初年度登録	H 26 10月	車名	WRX STI	ドア数	4	グレード	2.0 STI	駆動	4
型式	CBA-VAB	排気量	2,000 cc	燃料	ガソリン	駆動	4WD	内装	A B C
車種	乗用車	車歴	自家用	シフト	6MT	冷暖	AC	純正装備品 ○をつける	
走行距離	3万7千549 km	マイル	59,760 (交換)	※	(改ざん)	不明		純正ナビ	純正TV
外装色	元色 WRXブルーパール	色目	色替有	カラーNo.		内装色		純正AW	エアB
車台No.	VAB-003067	名義期間	月 日					TV種別 (社外品含む) ○をつける	
登録No.	抹消	リサイクル	無完全	12,500円納付済	未納			フルセグ	ワンセグ
定員	5人	積載量	kg	459	179	147		ナビ種別 (社外品含む) ○をつける	
輸入車のみ	モデル	年	輸入区分	ディーラー	並行	ハンド	左	HDD	DVD
	型式							DVD再生可	CD
セーリングポイント									
禁煙車 VOLK18インテアルミホイール フシツボマフラー カーボンGTウィング 強化クラッチ									

注意事項・不具合箇所	
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入	
シート小しわ	
ハーフレザーシート	
ホイールキズ	
各うすキズ	
ボディラッピング	
ドアミラー	キズ
工具	セビ
	ジャッキ
	フレ