

2014 Suzuki Alto 5D S		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-HA36S	658 cc		
YEAR / REG.	MILEAGE		
2014/12	73,422 km		
DOORS	SEATS		
5	4		
TRANSMISSION	FUEL		
AT	Petrol		
STEERING	EXTERIOR COLOR		
Right	Other		
BODY TYPE			
Other			
CHASSIS NO.	DIMENSIONS (L X W X H)		
HA36S-203652	340 × 148 × 148 cm		
INSPECTOR REPORT			
Torn seat cover. Exterior has fading, stains, and light A-grade scratches. Driver's mirror and wheel cover have A-grade scratches. Air bubbles are present in the lower glass.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式指字番号	車両区分番号	シリアル番号	評価点
初年度登録 年 H 26 月 12	車名 7人	ドア数 5	グレード S	駆動 4WD	3.5
型式 DBA-HA36S	排気量 660 cc	燃料 ガソリン	軽油	内装 A B C	
車種 R 09 年 12月	車歴 自家用	シフト AT	冷暖 AC	純正装備品 ○をつける	
走行距離 7 3 4 2 2 km	マイル \$ (交換) * (改ざん) # (不明)	純正ナビ	革シート	純正TV	
外装色 元色 ブロンズ 色替 色替無	カラーNo. 内装色	純正AW	エアB	TV種類 (社外品含む) ○をつける	
車台No. HA36S-203652	名室 期限	フルセグ	ワンセグ	アナログ	
登録No.	リサイクル 課託金	7,500円預託済	未預託	ナビ種類 (社外品含む) ○をつける	
定員 4 () 人	積載量 kg	諸元 長さ cm	幅 cm	HDD DVD SD	
輸入車のかい モデル 年式	生	輸入区分	ディーラー	並行	ハンドドル 左
セールスポイント ラジオ CD		後日発送品 ○をつける			
注意事項・不具合箇所		新車保証書 車庫取説			
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入					
シートカバー付き破れ					
外装アセ、シミ、うすA					
Dミラー、WカバーA					
下ガラス気泡有					
ドアミラー		キズ	ヒビ	ウレ	
工具		無	ジャッキ	無	