


2014 Suzuki Alto ECO ECO-L		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-HA35S		DISPLACEMENT 658 cc	
YEAR / REG. 2014/11		MILEAGE 50,000 km	
DOORS 5		SEATS 4	
TRANSMISSION AT		FUEL Petrol	
STEERING Right		EXTERIOR COLOR Red	
BODY TYPE Kei			
CHASSIS NO. HA35S-208662		DIMENSIONS (L X W X H) 340 × 148 × 152 cm	
INSPECTOR REPORT			
Light stains and scuffs on interior, seat stains, cargo area trim crack, right rear instrument panel repaired, left side touch-up paint present.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26 / 11月		メーカー スズキ		ドア枚数 5		ボディ形状 軽四		評価点 R	
		車名 アルトエコ		グレード ECO-L		駆動区分 2WD 4WD			
車歴 自用・その他 ()		排気量 660 CC		型式 DBA-HA35S		通称 型式		内装 A・B・C	
車検 - 年 - 月 / 日		燃料 ガソリン		ディーゼル		後日送り品 (保証書・取扱説明書等)			
走行 50,000 km		シフト フロア		AT					
外装色 レッド		カラーNo. ()		エアコン (A・B・AAG・WAG・())		新備品のみ O印 を記入			
()		内装色 ()		乗車定員 4人		P P AW		サンルーフ 革シート	
ハンド 左・右		輸入 区分		ディーラー 並行		リサイクル料 8,560円・預託金		エディック ABS ナビ TV	
セールスポイント リモコンキー レベライザー 純正CDオーディオ									
検査記入欄 内装薄汚れ・スレ シートシミ 荷室トリムワレ 右Rインパネ修復 左側面タッチUP有					修復歴 0. 無				
PW トビ石 傷A フレ 外装 A・B 小 A・B 曲 A・B エアロ A・B シリアル No.					A キズ U ヘコみ・凹み B キズ・ヘコみ P 色あせ・剥き G ガラスキズ W 補修跡 S サビ C 腐食 X 交換箇所 XX 交換車 登録No. 月 日 までにご名乗できる方 車体番号 HA35S-208662				
内装 ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺					長さ cm 幅 cm 高さ cm 最大積載量 Kg				