


2014 Suzuki Hustler G Turbo		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
MR31S	658 cc		
YEAR / REG.	MILEAGE		
2014	49,000 km		
DOORS	SEATS		
5	4		
TRANSMISSION	FUEL		
AT	Petrol		
STEERING	EXTERIOR COLOR		
Right	Brown		
BODY TYPE			
Kei			
CHASSIS NO.	DIMENSIONS (L X W X H)		
MR31S-801439	340 × 148 × 167 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Interior has scratches and dirt. Seats have scuffs and wrinkles. Exterior has minor and light scratches. AA rating 4.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H26 / 一月	メーカー スズキ 車名 ハスラー	ドア枚数 5	ボディ形状 軽四	評価点 4
車種 自家用・その他 ()	排気量 660 cc	型式 MR31S	通称 軽四	内装 A・B・C
車検 9年1月 / 抹消	燃料 ガソリン	ディーゼル	検出通り品 (保証書・取扱説明書 等)	
走行 49,000 km	インパネ	AT		
外装色 アーバンブラウンパールメタリック	カラーNo. AAG・WAG・()	エアコン	装備品のみ ORP を記入	
()	内装色 4人	乗車定員	PS	AW
左・右 左・右	ディーラー・車行	8,860円・預託金	エブリック	TV
セールスポイント CD/ETC横滑り防止装置 (ESC) / HID・キセノン・ ディスチャージ/運転席エアバック/盗難防止システム/ス マートキー/キーレスエントリー/ABS/助手席エアバッ ク/メモリーナビ/衝突被害軽減ブレーキ/衝突安全ボ ディ/アイドリングストップ/ターボ/シートヒーター/ベン チシート/DVD再生/ミュージックサーバー				
検査記入欄 内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ AA評価4点仕入れ				
				
修復歴 有・無				
A キズ U ヘッドライト B キズ・ヘッド C 色あせ・ボケ D ガラスキズ W 補修跡 S サイズ C 腐食 X 交換済 XX 交換済				
登録No. 月 日 までにも名義できる方				
車体番号 MR31S-801439				
シリアル No.				
長さ cm 幅 cm 高さ cm 最大積載量 Kg				