

ORIGINAL JAPANESE AUCTION SHEET

注意事項：不適合箇所

検査員記入欄：修復後「有」の場合は修復箇所・交換箇所を記入

The diagram shows a top-down view of a vehicle chassis. Inspection points are labeled A1 at various locations along the frame rails and crossmembers. Point B1 is located near the front suspension area. Point C1 is indicated by a circle and dimension line at the bottom right corner. Vertical dimensions of 9mm are shown on both sides.

F/Aユーザー 名	E/E	C/C