

2014 Suzuki Spacia X		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
MK32S	658 cc		
YEAR / REG.	MILEAGE		
2014/12	42,933 km		
DOORS	SEATS		
5	4		
TRANSMISSION	FUEL		
AT	Petrol		
STEERING	EXTERIOR COLOR		
Right	Black		
BODY TYPE			
Kei			
CHASSIS NO.	DIMENSIONS (L X W X H)		
MK32S-229459	340 × 148 × 174 cm		
SALES POINTS			
Back Camera		Navigation System	
INSPECTOR REPORT			
Minor exterior scratches, left power mirror faulty, floor panel seal cracked.			

ORIGINAL JAPANESE AUCTION SHEET

H26 / 12月		メーカー スズキ		ドア枚数 5	ボディ構造 軽四	評価点 4
		車名 スペースシア		グレード X	駆動区分 2WD 4WD	
車種 自家用・その他 ()	排気量 660 cc	型式 MK32S	通称 A	内装 A	③	C
車検 - - / - - 年 - - 月 - - 日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)			
走行 口内にマークを記入 (金・交換・点検・点検)	シフト フロア	AT				
外装色 ブラック I I	カラーNo. ()	エアコン A・AAG・WAG・()	新着品のみ O印 を記入			
()	内装色 ()	乗車定員 4 人	⑤	⑥	AW	サンルーフ
ハンドル 左・右	輸入 区分	ディーラー ・ 並行	9,770 円	⑦	⑧	⑨
セールスポイント			A1 B1 B1 B1 A1 W2 A1 U1 A1			
フルフラットバックカメラ/運転席エアバック/盗難防止システム/スマートキー/エコカー減税対象車/キーレスエントリー/ABS/助手席エアバック/ナビ/ワンセグTV/衝突安全ボディ/アイドリングストップ			修復歴 有 . ⑩			
特記事項			A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ G ガラスキズ			
左電格ミラー不良 フロアパネルシール割れ			W 補修跡 S サビ C 腐食 X 交換済 XX 交換済			
検査記入欄			登録No. 月 日 までに名変更できる方			
外装うす傷 ミラー電格左不良 フロアパネルシール割れ			定価 MK32S-229459			
FW トピ石 備A ワレ	外装 小	ホイール	エアロ	シリアル No.		
内装 ヨグレ シミ ヤブレ	コゲ	コゲ穴	オーディオ穴	スレ	長さ cm	幅 cm