

2014 Toyota Harrier Elegance		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-ZSU60W	DISPLACEMENT 1,986 cc		
YEAR / REG. 2014/03	MILEAGE 95,950 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE SUV		
CHASSIS NO. ZSU60-0011064	DIMENSIONS (L X W X H) 472 × 184 × 169 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Power Seats (Front) (Front Passenger S...		Back Camera	
Navigation System			
INSPECTOR REPORT			
Right floor distortion, right inner panel repair marks, end panel XX, seat stains and wear, interior dirt, steering wheel scuffs, side mirror A, light scratches on exterior.			

ORIGINAL JAPANESE AUCTION SHEET

型式番号 H26 / 3月	メーカー トヨタ	ドア数 5	ボディタイプ SUV/クロカン	評価点 R
車名 ハリアー	グレード エレガンス	駆動方式 4WD	燃費区分 4WD	
車種 自家用・その他 ()	排気量 2000 CC	型式 DBA-ZSU60W	通称 4WD	内装 A・B・C
車検 - - 年 月	燃料 ガソリン	ディーゼル ハイブリッド ()	登録番号 後部 前部	
走行 95,950 km	シフト フロア	AT	修理履歴 O印を記入	
外装色 パール (070)	カラーNo. 070	エアコン AG・AC・WAG ()	装備品のみ O印を記入	
オプション 左・右・後部 ディーラー・走行	リサイクル料 13,690円	登録料 13,690円	エアロ エアロ	エアロ
セールスポイント		修復歴 O印を記入		
検査記入欄		A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損		
Rフロアヒズミ、Rインナー修正跡、エンドパネルXX、シートシミ・ヘタリ、室内ヨゴレ、ハンドルスレ、サイドミラーA、外装うすい線キズ、		名義中		
		月 日 まで名義できる方		
		ZSU60-0011064		
内装 内装	外装 外装	ボディ ボディ	エンジン エンジン	最大積載量 Kg
472 cm	183 cm	169 cm		