

2014 Toyota PASSO X L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-KGC30	DISPLACEMENT 996 cc		
YEAR / REG. 2014/09	MILEAGE 15,830 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Hatchback		
CHASSIS NO. KGC30-0197137	DIMENSIONS (L X W X H) 364 × 167 × 154 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Wheel caps, door mirror (minor scratch), various scratches, dents, and light scratches.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26 9月		メーカー トヨタ		ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4																				
車名 パッソ		グレード X Lパッケージ		駆動区分 4WD																						
車種 自家用・その他 ()	排気量 1000 cc	型式 DBA-KGC30	燃費 A・C	内装 A・C・C																						
車検 - - 年 月	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書等)																							
走行 15,830 km	シフト インパネ	AT																								
外装色 シルバー	カラーNo. (S28)	エアコン	新車品のみ O印 を記入																							
内装色 ()	乗車定員 5人	AW	サンルーフ	革シート																						
左・右 左	輸入 区分	ディーラー	並行	リサイクル料	8,040円	預託金																				
セールスポイント キーフリー・ナビ・TV・アイドリングストップ・ヘッドライトレベライザー			修復歴 有・無																							
検査記入欄 ホイールCP、DミラーA 各キズ、U、ウスA			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘビキズ</td><td>B</td><td>キズ・ヘビキズ</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘビキズ	B	キズ・ヘビキズ	P	色あせ・汚れ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘビキズ	B	キズ・ヘビキズ	P	色あせ・汚れ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
登録No. KGC30-0197137			名義中 月 日 までに名義できる方																							
シリアルNo. KGC30-0197137			最大積載量 Kg																							
FW (トビ)	備A	ワレ	外装 小	内装 小	エアロ A・ワレ	シリアル No.																				
内装 (ヨシ)	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	最大積載量 Kg																				