

2014 Toyota REGIUS ACE VAN 3.0 Super GL		OVERALL	
		R	
EXTERIOR		INTERIOR	
-		-	
MODEL CODE QDF-KDH201V		DISPLACEMENT 2,982 cc	
YEAR / REG. 2014		MILEAGE 167,000 km	
DOORS 5		SEATS 5	
DRIVETRAIN 2WD (FR)		TRANSMISSION AT	
FUEL Diesel		STEERING Right	
EXTERIOR COLOR Black		BODY TYPE Minivan	
CHASSIS NO. KDH201-0140693		DIMENSIONS (L X W X H) 469 × 169 × 198 cm	
INSPECTOR REPORT			
Left side body panels (excluding front pillar) show signs of repair and repainting. Repair history is unknown due to potential damage to the left rear inner panel. Left rear fender is distorted. Cracks on both sides of the rear bumper. Tailgate has a dent and some paint peeling. Other scratches and minor dents observed. Interior trim shows wear and tear from age and commercial use.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26 / 一月		メーカー トヨタ		ドア枚数 5		ボディ形状 ミニバンワンボックス		評価点 R	
車名 レジアスエースバン		グレード 3.0スーパーGL		駆動方式 2WD		4WD			
車種 自家用・その他 ()		排気量 2980 CC		型式 QDF-KDH201V		通称 型式		内装 A・B・C	
車検 - 年 / 月		燃料 ガソリン		変速機 オートマ		後日添付品 (保証書・取扱説明書等)			
走行 167,000 km		シフト AT		外装色 ブラックマイカ		カラーNo. Aa・AAG・WAG・()		装備品のみ O印 を記入	
内装色 ()		エアコン		PS		PW		AW	
左・右		ディーラー		走行		エアバック		ABS	
9,550円		リサイクル料		ナビ		TV		キーレス	
セールスポイント		検査記入欄		修理歴		A1		A1	
		・左側面の外板(フロントピラーを除く)に板金塗装痕が確認できました。左リアインサイドパネルに損傷の可能性があるので、修理歴は不明としております。		A		U		H	
		・左Rフェンダーに凸み		W		S		C	
		・Rバンパー左右に凸み		X		P		A	
		・バックドアに凹み、一部塗装剥け		XX		Q		G	
		その他、錆傷・えくぼが見受けられました。		名義中		月		日	
		経年のダメージやお仕事での使用に伴う内装の傷などのダメージ		登録No.		月		日	
				車検		KDH201-0140693			
PW		A		W		S		C	
内装		シロ		ヤブ		コガ		コガ	
469 cm		169 cm		198 cm		Kg			