


2014 Toyota REGIUS ACE VAN DX 4WD		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDF-KDH206V	DISPLACEMENT 2,982 cc		
YEAR / REG. 2014/03	MILEAGE 135,870 km		
DOORS 5	SEATS 6		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Minivan		
CHASSIS NO. KDH206-6008265	DIMENSIONS (L X W X H) 469 × 169 × 198 cm		
INSPECTOR REPORT			
Rear panel dent, engine oil leak, many small dents and some paint damage in cargo space, many dents on roof.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26/3月	メーカー トヨタ	ドア枚数 5	ボディ形状 バン	評価点 3
車名 レジアスエースバン	グレード DX 4WD	駆動区分 2WD 4WD		
車歴 自家用・その他()	排気量 2980 CC	型式 LDF-KDH206V	通称 型式	内装 A・B・C
車検 -年-月-日	燃料 ガソリン	変速機 ハイブリッド	後日送り品(保証書・取扱説明書等)	
走行 135,870 km	シフト インパネ	AT		
外装色 シルバー	カラーNo. 1E7	エアコン A・B・AAG・WAG・()	新備品のみ O印 を記入	
()	色車検はO印に 「色検」と記入	内装色	乗車定員 6人	P3 P4 AW サンルーフ 革シート
ハンドル 左・右	輸入 区分	ディーラー 並行	リサイクル料 10,430円・預託無	エエ/アップ AS6 ナビ TV キーレス
セールスポイント ワンオーナー キーレス ビルトインETC 寒冷地仕様 左右アウトサイドモール				
検査記入欄 R/パネルU E/Gオイル漏れ 荷室AU多、1部Pアト ルーフU多		修復歴 有・無 A キズ U ヘコみ・凹み B キズ・ヘコみ P 色あせ・剥落 G ガラスキズ W 補修跡 S サビ C 腐食 X 交換箇所 XX 交換車 登録No. 月 日 まで(に)名義できる方 車体 番号 KDH206-6008265 シリアル No.		
PW トド石	ワレ	外装 A・B A・C A・D A・E A・F A・G A・H A・I A・J A・K A・L A・M A・N A・O A・P A・Q A・R A・S A・T A・U A・V A・W A・X A・Y A・Z	ホイール A・B A・C A・D A・E A・F A・G A・H A・I A・J A・K A・L A・M A・N A・O A・P A・Q A・R A・S A・T A・U A・V A・W A・X A・Y A・Z	エアロ A・B A・C A・D A・E A・F A・G A・H A・I A・J A・K A・L A・M A・N A・O A・P A・Q A・R A・S A・T A・U A・V A・W A・X A・Y A・Z
内装 ヨコシ	シミ	コゲ	コゲ穴	オーディ穴
長さ 469 cm	幅 169 cm	高さ 198 cm	最大積載量 1000 kg	