

2014 Toyota VOXY ZS		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-ZRR80W	1,986 cc		
YEAR / REG.	MILEAGE		
2014/08	88,000 km		
DOORS	SEATS		
5	7		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
ZRR80-0049761	471 × 173 × 183 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Drive...	
Back Camera		Navigation System	
INSPECTOR REPORT			
Interior has light dirt and scuffs. Rear spoiler and mirror A have paint peeling. Interior odor present. Front bumper bottom has a minor scratch (A). Front windshield has a stone chip. Interior also has dirt, and scuffs are present around the audio hole.			

印刷年度登録	トヨタ		ドア数	5	ボディタイプ	ミニバンワンボックス	評価点	4																				
H26 / 8月	ヴォクシー		グレード	Z S		燃費区分 2WD 4WD																						
車種	自家用・その他 ()		排気量	2000	型式	DBA-ZRR80W	国産車	A () C																				
車検	- 年 / 月		燃料	ガソリン	ディーゼル	費用区分 (保証費・取扱説明書等)																						
走行			インパネ		AT																							
外装色			ブラック		新車品のみ O印 を記入																							
内装色			()		7 人																							
左 / 右			ディーラー		12,470 円																							
セールスポイント			スマートキー 両Pスラ ナビ フルセグ Bカメラ フリップダウンモニター ETC ウインカーミラー 純正AW																									
検査記入欄																												
内装薄汚れ・スレ Rスポリパグ ミラー・A・Pハグ 庫内匂い 庫内下ア			<table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>ヘコみやサレ</td> <td>B</td> <td>キズ・ヘコみ</td> <td>P</td> <td>色あせ・汚れ</td> <td>G</td> <td>ガラスキズ</td> </tr> <tr> <td>W</td> <td>傷跡跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> </table>						A	キズ	U	ヘコみやサレ	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ	W	傷跡跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみやサレ	B	キズ・ヘコみ	P	色あせ・汚れ	G	ガラスキズ																			
W	傷跡跡	S	サビ	C	腐食	X	交換済	XX	交換済																			
車検番号			ZRR80-0049761																									
車検			2026年 月 日																									
車検			ZRR80-0049761																									
車検			ZRR80-0049761																									