

2014 Volkswagen VW Golf GTI GTI Performance		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
ABA-AUCHH	1,984 cc		
YEAR / REG.	MILEAGE		
2014/12	36,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WVWZZZAUZFW124499	428 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Navigation System	
INSPECTOR REPORT			
AIS assessed vehicle. Mirror A, small damage on pillar interior trim A. Small scuff on steering wheel, right side & BO repair marks. Exterior has thin line scratches and small scratches. Front bumper underside A has medium damage, with stone chips around the front. Front glass has medium stone chips.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H26 12月	メーカー フォルクスワーゲン 車名 ゴルフ	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 4.5
車種 自家用・その他 ()	排気量 2000 cc	型式 ABA-AUCHH	内装 A・⑤・C	
車検 - - 年 / 月 / 日	燃料 ガソリン	グレード GTI パフォーマンス	後付選用品 (保証書・取扱説明書等)	
走行 36,000 km	シフト フロア 6 AT			
外装色 ホワイト	カラーNo. ()	エアコン AG・⑥・WAG・()	新着品のみ・①印を記入	
内装色 ()	乗車定員 5人	⑤	サンルーフ	革シート
①左・②輸入品 ③右・④走行 ⑤14,940円・⑥販売税	⑦エンジン	⑧ABS	⑨TV	⑩⑪
セーフティポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/メモリーナビ/衝突被害軽減ブレーキ/ETC/アイドリングストップ/スマートキー/盗難防止システム/オートクルーズコントロール/H I D・キセノン・ディスチャージ/横滑り防止装置 (ESC) /D V D再生/CD/障害物センサー/M Tモード付き				
修復歴 有・⑫				
検査記入欄 AIS査定車 ミラーA ビラー内張りA<小> ハンドル握れ<小> 右側面&B O修理跡 外装腐蝕キズ 外装小傷有 Fバンパ下面A<中> F懸り飛び有 Fガラス飛び<中>				
A キズ B ヘッドライト C キズ・ヘッドライト D 色あせ・汚れ E ガラスキズ W 腐蝕跡 F サビ G 腐食 H 交換機 I 交換機 J 交換機				
登録月 日 年 名義中				
車検番号 WVVWZZZAUZFW124499				
内装 FR ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺	FR ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺	FR ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺	FR ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺	FR ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺