


2014 Volkswagen VW Golf GTI Performance		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
ABA-AUCHH	1,984 cc		
YEAR / REG.	MILEAGE		
2014/12	69,531 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Gray	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WVWZZZAUZFW117444	428 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26 / 12月		メーカー フォルクスワーゲン		ドア枚数 5		ボディ形状 コンパクト/ハッチバック		評価点 4.5																				
車名 ゴルフGTIパフォーマンス		グレード 2WD		駆動区分 4WD																								
車種 自家用・その他()	排気量 2000 cc	型式 ABA-AUCHH	通称 型式	内装 A・⑨・C																								
車検 - - 年 / 月 / 日	燃料 ハイブリッド()	ディーゼル		後日選り品(保証書・取扱説明書等)																								
走行 69,531 km	シフト フロア	AT																										
外装色 ガンメタ	カラーNo. ()	エアコン AG・⑨・WAG・()		装飾品のみ O印 を記入																								
5人乗車(11人以内) (色黒)は記入	内装色 ()	乗車定員 5人		⑨	⑨	AW	サンルーフ	革シート																				
左・右 左・右	輸入区分 デ	並行	14,940円・預託金	エアロ	⑨	ナビ	TV	キーレス																				
セールスポイント																												
検査記入欄				<table><tr><td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラスキズ</td></tr><tr><td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr></table>					A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ																			
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																			
登録No.				名 変 中																								
月 日				までに名変できる方																								
車検番号				WVWZZZAUZFW117444																								
FW	⑨	備A	フレ	外装	小	ホイール	エアロ	シリアル No.																				
内装	⑨	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	⑨	車検																				
				長さ		幅	高さ	最大積載量																				
				cm		cm	cm	kg																				