

2014 SUBARU WRX S4 2.0GT-S EyeSight		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-VAG	DISPLACEMENT 1,998 cc		
YEAR / REG. 2014/12	MILEAGE 110,964 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Sedan		
CHASSIS NO. VAG-005056	DIMENSIONS (L X W X H) 459 × 179 × 147 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Adaptive Cruise Control Navigation System		STI Pre-Collision Braking Cruise Control	
INSPECTOR REPORT			
Underbody rust/corrosion. Engine oil seepage. Heavy seat scuffs. Interior dirty. Door panel medium scratches. Carpet scuffs.			

出品票		販売店コード 17724		1002		インボイス番号	
初年度登録 H 26 型式 WRX S4 ドア数 4 グレード 2.0GT-S EyeSight 駆動 2WD		車名 DBA-VAG		年式 2.000		燃料 ガソリン	
月 12		日 0		年 20		平成 年 月 日	
車種 R 09		12月		車種 自動車		シフト CVT	
走行距離 1 万 0 千 km		色 白		マイル (改ざん)		年 (改ざん)	
外装色 光沢 白		色 白		カラーNo.		内装色 白	
車台No. VAG-005056		車種 白		年式 2000		月 日	
登録No. 札幌 351 ち 1128		リサイクル料 12,500円		消費税 147円		車検料 147円	
定額 5 () 円		車検料 147円		消費税 147円		車検料 147円	
輸入車のみ 型式		輸入区分		ディーラー		走行 ハンドル	
セルシオメント ST1277B 禁煙車 純正純正 フォクシー ETC レーダーセンサー付 LEDヘッドライト		保証書 保証書		保証書 保証書		保証書 保証書	

注意事項、不具合報告

検査書記入欄：修繕歴「有」の場合に修繕箇所・交換箇所を記入

下廻り S 有

エンジン廻り 汚れ

シートすれ

室内汚れ

ドア内張傷

カーペットすれ

ドアノブ	キズ	ヒビ	フレ
上取	無	ジャンシ	無