

2014 SUBARU WRX STI STI TypeS		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-VAB	DISPLACEMENT 1,994 cc		
YEAR / REG. 2014/09	MILEAGE 113,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Sedan		
CHASSIS NO. VAB-002434	DIMENSIONS (L X W X H) 460 × 180 × 148 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Repair history A: Right rear inner underbody damage, Trunk floor underbody damage. Medium wear on driver's seat and door trim. Heavy wear on steering wheel. Wear on shift knob and parking brake knob. End panel side and trim repair marks. Center pillar seat belt area issue. Right fender has removal marks. Front underbody scrapes.			

[illegible]