

2014 SUBARU XV Hybrid 2.0i-L EyeSight		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-GPE	DISPLACEMENT 1,995 cc		
YEAR / REG. 2014/01	MILEAGE 98,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Green	BODY TYPE SUV		
CHASSIS NO. GPE-011755	DIMENSIONS (L X W X H) 445 × 178 × 160 cm		
SALES POINTS			
Alloy Wheels Navigation System		Adaptive Cruise Control	
INSPECTOR REPORT			
Light dirt and scuffs on interior, seat stains and scuffs, headliner dirt, interior trim A, steering wheel scuffs, light stay X, 1 point scratch on front grille.			

期年次登録 H26 / 1月		メーカー スバル 車名 XVハイブリッド		ドア枚数 5 ボディ形状 SUV/クロカン		評価点 3.5	
車種 自動車・その他		排気量 2000 CC		型式 DAA-GPE		内装 A・C	
年式 - 年 - 月 - 日		燃料 ガソリン ハイブリッド		ディーゼル		後日取り品 (保証書・取扱説明書等)	
走行 98,000 km		シフト フロア		AT		新備品のみの印を記入	
外装色 グリーン		カラーNo. AG・BG・WAG・C		エンジン 5 人		新備品のみの印を記入	
()		内装色 5		車検費用		新備品のみの印を記入	
シート 左・右		輸入区分 ディーラー		走行 12,030 km		エアコン TV	
セールスポイント		スマートキー メモリーナビ ETC レベライザー HID ウィンカーミラー 純正AW		修復歴 有 ()			
検査記入欄		内装確認、スレ シートシミ、スレ 欠損、汚れ 内装A ハンドルスレ ライトスターX ドア確認		外装確認、スレ シートシミ、スレ 欠損、汚れ 内装A ハンドルスレ ライトスターX ドア確認			
内装確認、スレ シートシミ、スレ 欠損、汚れ 内装A ハンドルスレ ライトスターX ドア確認		外装確認、スレ シートシミ、スレ 欠損、汚れ 内装A ハンドルスレ ライトスターX ドア確認		車検費用			
年式 GPE-011755		車検費用		車検費用			