


2015 Audi Audi RS e-tron GT Cooper		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-XM15	DISPLACEMENT 1,498 cc		
YEAR / REG. 2015/09	MILEAGE 69,880 km		
DOORS 3	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Hatchback		
CHASSIS NO. WMWXM520102D00261	DIMENSIONS (L X W X H) 384 × 173 × 142 cm		
SALES POINTS			
Alloy Wheels		Back Camera	
Cruise Control		Navigation System	
INSPECTOR REPORT			
Minor scratches, minor interior stains, minor alloy wheel scratches			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27/9月	メーカー MINI MINI	ドア枚数 3	ボディ形状 コンパクトハッチバック	評価値 4.5																																								
車種 自家用・その他 ()	排気量 1500 cc	型式 DBA-XM15	駆動方式 2WD 4WD	内装 A・B・C																																								
車検 - 年 - 月 / 日	燃料 ガソリン	ディーゼル	後付選用品 ()	取換要																																								
走行 69,880 km	フロア 6 AT	エアコン	サンルーフ	革シート																																								
外装色 ダークブルーツートン	カラーNo.	AG・AG・WAG ()	装備品のみ O印 を記入																																									
内装色 ()	乗車定員 4 人	リサイクル料	17,700円	預託料																																								
セールスポイント	☆ナビ ☆バックカメラ ☆Bluetoothオーディオ ☆オートLEDヘッドライト ☆MINIドライビングモード ☆ディスプレイLEDリングライト ☆ETC ☆デジタルインナーミラー 																																											
検査記入欄	各キズ 小 内装汚れ 小 AWキズ 小 <table><tr><td>A</td><td>キズ</td><td>U</td><td>ヘビイオサレ</td><td>B</td><td>キズ・ヘコ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td></tr><tr><td>W</td><td>補修跡</td><td>S</td><td>ヤビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr></table> 登録No. 月 日 までに名義できる方 車体番号 WMWXM520102D00261 <table><tr><td>FW</td><td>トビ</td><td>傷A</td><td>ワレ</td><td>外装</td><td>小</td><td>ホイール</td><td>エアロ</td><td>シリアル</td><td>No.</td></tr><tr><td>内装</td><td>シロ</td><td>ヤブレ</td><td>コガ</td><td>コガ穴</td><td>オーディオ穴</td><td>スレ</td><td>取替</td><td>長さ</td><td>最大積載量</td></tr></table>				A	キズ	U	ヘビイオサレ	B	キズ・ヘコ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	ヤビ	C	腐食	X	交換済	XX	交換済	FW	トビ	傷A	ワレ	外装	小	ホイール	エアロ	シリアル	No.	内装	シロ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	取替	長さ	最大積載量
A	キズ	U	ヘビイオサレ	B	キズ・ヘコ	P	色あせ・ボケ	G	ガラスキズ																																			
W	補修跡	S	ヤビ	C	腐食	X	交換済	XX	交換済																																			
FW	トビ	傷A	ワレ	外装	小	ホイール	エアロ	シリアル	No.																																			
内装	シロ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	取替	長さ	最大積載量																																			