

2015 BMW BMW 3series Touring 320d Touring Luxury		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-3D20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2015/08	MILEAGE 47,271 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Station Wagon		
CHASSIS NO. WBA3K32030K474435	DIMENSIONS (L X W X H) 463 × 180 × 146 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Pre-Collision Braking Cruise Control Navigation System		Roof Rails Power Seats (Front) Adaptive Cruise Control Back Camera	
INSPECTOR REPORT			
Exterior stains, minor seat wrinkles, minor seat scuffs, interior trim scratches, window film applied.			

初年度登録		メーカー BMW		ドア数 5		ボディ形状 ステーションワゴン		呼称点	
H27 / 8月		車名 3 シリーズ		グレード 320d ツーリン グラグジュアリー		駆動方式 2WD 4WD		4	
車種 自家用 ・ その他 ()	排気量 2000	型式 CC	LDA-3D20	運転形式			内装 A・C・G		
年式 - 年 月 日	燃料 ガソリン	変速機 式(変速機)	後付選り品 (保証書・取扱説明書等)						
走行 () []内にマークを記入し、交換 ※(盗難時※) 印			シフト						
走行 [] 万 [] 千 [] 百 [] 十 [] 円	マイル AT								
外観色 シロ	カラーNo. ()	エンジン QD・AAG・WAD・()	新着商品の O印 を記入						
()	内装色	乗車人数 人	P	C	A	サンルーフ	革シート		
左・右・後	輸入国 G	走行	20,250 円	販売店 エフエック	S	ナビ	TV	キーレス	
セールスポイント									
ブッシュスタート									
検査記入欄									
外装仕様、シートしわ小、シートすれ小、室内内張傷、ガラスフィルム張									
修理履歴									
有。 (S)									
A	ボディ	U	ヘッパボルト	B	キズへ補正	熱変色・変色	G	ガラスキズ	
B	修繕部	C	サビ	D	腐食	X	交換済	XX	交換済
月 日									名義主
車体番号 WBA3K32030K 474435									
FW ()	備A	フレ	内装	小 ()	オイル ()	エアロ			
内装 ()	シロ	ヤレ	コガ	コガ穴	オーデイオ	ウレ			
最大積載量									