

2015 BMW BMW X1 sDrive 18i xLine		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-VL18	DISPLACEMENT 1,995 cc		
YEAR / REG. 2015/07	MILEAGE 53,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE SUV		
CHASSIS NO. WBAVL32050VZ19715	DIMENSIONS (L X W X H) 449 × 180 × 158 cm		
SALES POINTS			
Alloy Wheels Back Camera		Roof Rails Navigation System	
INSPECTOR REPORT			
Repair marks present, minor aluminum scratches. Slight dullness on roof rails and both headlights. Minor wrinkles and scuffs on driver's seat and trunk.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H27 7月	メーカー BMW	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 X 1	グレード sドライブ 18i xライン ルー フレール 18アルミHID黒ハー フレザーHDDナビモニター	駆動方式 4WD	燃費区分 4WD	
車種 自家用・その他 ()	排気量 2000 cc	型式 CBA-VL18	登録 形式	内装 A・B・C
車検 - 年 - 月 / 日	燃料 ガソリン	ディーゼル	検日満期品 (保証書・取扱説明書 等)	
走行 53,000 km	シフト フロア 6 AT			
外装色 アルビノ・ホワイトIII	カラーNo. ()	エアコン	新着品のみ O印 を記入	
()	色車検はO印に 「色検」を記入	乗車定員 5人	サンルーフ	高シート
小 型車	左・右 ステアリング	20,320円	ナビ	TV
セールスポイント				
キーレスエントリー/ABS/運転席エアバック/助手席エ アバック/サイドエアバック/カーテンエアバック/HDD ナビ/ETC/スマートキー/HID・キセノン・ディス チャージ横滑り防止装置(ESC)/DVD再生/ミュー ジックサーバー/CD/バックカメラ/障害物センサー/パ キングアシスト/定期点検記録簿				
検査記入欄				
補修跡有り、アルミ傷少 ルーフレール、左右ヘッドライトくすみ少 運転席、トランクシワ擦れ傷少				
車検No. 月 日 までには名置できる方				
車体 番号 WBAVL32050VZ19715				
FW トヨタ	機A 三菱	フレ ヤマハ	外装 コガ	小 コガ
内装 コガ	シス コガ	ヤブレ コガ	コガ	オーデウス
シリアル No.	エンジン No.	変速機 No.	高S cm	高S cm
高S cm	高S cm	高S cm	最大積載量 kg	