

2015 BMW BMW X1 sDrive20i xLine		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-VL20	1,997 cc		
YEAR / REG.	MILEAGE		
2015/08	68,820 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FR)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBAVL920X0VZ99998	449 × 180 × 155 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Back Camera		360° Camera	
Navigation System			
INSPECTOR REPORT			
Minor scratches, minor interior stains, minor alloy wheel scratches			

初年度登録	メーカー BMW	ドア数 5	ボディ形状 SUV/クワゴン	評価点
H27 / 8月	車名 X 1	グレード S Drive 20i xラインナビ パックカメラBluetoothオーディオ	駆動方式 2WD 4WD	9.5
車種 自家用・その他()	排気量 3000 CC	型式 DBA-VLZ20	温熱空調	内装 A・⑨・C
年式 - - 年	燃料 ガソリン	ディーゼル	償還月割金（保証費・取扱説明書等）	
走行 口にマーク付輸入車（※） ミッドナイト・ブルーメタリック カラーNo. （ ） 右ハンドル（HAC） （ ） 左ハンドル（HAC）	シフト フロア 8 AT	エンジン AD・6速・WAG・（ ）		
外観色 ミッドナイト・ブルーメタリック	カラーNo.	エナジ AD・6速・WAG・（ ）	装備品のみのO印を記入	
（ ）	内装色	標準定員 5人	(B) (F) (A) サルーフ	革シート
（ ）	（ ）	（ ）	(B) (F) (A) TV	キース
セーリングポイント				
☆ナビ ☆バックカメラ ☆Bluetooth ☆ ハーフレザーシート ☆スマートキー ☆オートキスノ ンライト ☆クリアランスソナー				
検査記入欄				
各キズ 小 内装汚れ 小 AWキズ 小				
PW (E) 備A ワレ 外装 小 A・U オイル 曲 A・フレ エプロ シリアル No.	A キズ U ハードウェア B キズヘウコ P 色あざやサ G ガラスキズ W 傷跡 E サビ C 腐食 X 交換部 XI 交換済	登録地 月 日 家でに名義で所有する		
内装 (G) シロ ヤレ コグ ゴグス オーディオX スレ	車体番号 WBAVL920X0VZ99998			
車種	最大積載量			