

|                                                                                                                                                                           |                                              |                                     |          |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|-------------------------------------|----------|
| 2015 BMW_Mini BMW Mini Clubman<br>Cooper Clubman                                                                                                                          |                                              | OVERALL                             |          |
|                                                                                                                                                                           |                                              | 4                                   |          |
|                                                                                                                                                                           |                                              | EXTERIOR                            | INTERIOR |
|                                                                                                                                                                           |                                              | -                                   | -        |
| MODEL CODE<br>LN15                                                                                                                                                        | DISPLACEMENT<br>1,498 cc                     |                                     |          |
| YEAR / REG.<br>2015/12                                                                                                                                                    | MILEAGE<br>36,104 km                         |                                     |          |
| DOORS<br>5                                                                                                                                                                | SEATS<br>5                                   |                                     |          |
| DRIVETRAIN<br>2WD (FF)                                                                                                                                                    | TRANSMISSION<br>AT                           |                                     |          |
| FUEL<br>Petrol                                                                                                                                                            | STEERING<br>Right                            |                                     |          |
| EXTERIOR COLOR<br>Gray                                                                                                                                                    | BODY TYPE<br>Station Wagon                   |                                     |          |
| CHASSIS NO.<br>WMWLN320502B34097                                                                                                                                          | DIMENSIONS (L X W X H)<br>427 × 180 × 147 cm |                                     |          |
| SALES POINTS                                                                                                                                                              |                                              |                                     |          |
| Alloy Wheels<br>Back Camera                                                                                                                                               |                                              | Cruise Control<br>Navigation System |          |
| INSPECTOR REPORT                                                                                                                                                          |                                              |                                     |          |
| Exterior: Noticeable scratches and dents have been repaired, but minor scratches and dents remain.<br>Interior: Some areas have noticeable dirt. Frame: No abnormalities. |                                              |                                     |          |

[illegible]