

2015 BMW_Mini MINI Cooper		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE XS15	DISPLACEMENT 1,498 cc		
YEAR / REG. 2015/02	MILEAGE 72,450 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Hatchback		
CHASSIS NO. WMWXS520302B36713	DIMENSIONS (L X W X H) 400 × 173 × 145 cm		
SALES POINTS			
Alloy Wheels Back Camera		Sunroof Navigation System	
INSPECTOR REPORT			
Minor scuffs on seats, minor scratches on pillar trim, minor scuffs on steering wheel, TR repair marks, minor scratches on exterior, cloudiness/whitening.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H27/2月	メーカー MINI	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4.5
車名 MINI	グレード クーパー	駆動方式 2WD	4WD	
車種 自家用・その他()	排気量 1500 cc	型式 XS15	選装 型式	内装 A・B・C
車検 -年-月/日	燃料 ガソリン	ディーゼル	後日選り品(保証書・取扱説明書等)	
走行 72,450 km	シフト フロア 6 AT			
外装色 エレクトリックブルー/ホワイト	カラーNo. ブラック	エアコン	新着品のみ O印 を記入	
内装色 ()	乗車定員 5人	CD/D	サンルーフ	高シート
小シフト 左・右	輸入 国	18,960円	エレクトリック	TV
セールポイント				
CD/バックカメラ/ETC/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/HDDナビ/アイドリングストップ/ターボ				
検査記入欄				
シート破れ(小) ビーム内抵衝(小) ハンドル破れ(小) TR修理跡 外装小傷有 屋根/白				
修復歴 有・無				
A キズ U ヘコみ/サシ B キズ/ヘコみ P 色あせ/汚れ Q ガラスキズ W 腐蝕跡 S サビ C 腐食 X 交換品 XX 交換済				
登録No. 月 日 までに名義できる方				
車体番号 WMWXS 520302B36713				
FW トボ石 傷A フレ 外装 小 ホイル エアロ シリアル No. A・U A・曲 A・フレ				
内装 コゴレ シミ ヤブレ コガタ オーディオ穴 スレ				
重量 長さ 幅 高さ 最大積載量				