


2015 Daihatsu Copen Robe		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LA400K		DISPLACEMENT 658 cc	
YEAR / REG. 2015/09		MILEAGE 69,539 km	
DOORS 2		SEATS 2	
DRIVETRAIN 2WD (FF)		TRANSMISSION AT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR Other		BODY TYPE Kei	
CHASSIS NO. LA400K-0012252		DIMENSIONS (L X W X H) 340 × 148 × 128 cm	
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Seat wrinkles, minor scratch on door mirror (A), many minor scratches on exterior top (A), underbody painted, missing wheel center cap.			

ORIGINAL JAPANESE AUCTION SHEET

H27/9月		メーカー ダイハツ		ドア枚数 2		駆動方式 軽四		評価点 4																					
車名 コペン		グレード ローブ		駆動方式 2WD 4WD																									
車種 自家用・その他 ()		排気量 650		型式 DBA-LA400K		通称 型式		内装 A・B・C																					
車検 8年9月		燃料 ガソリン		ディーゼル		燃料 ハイブリッド ()		検出通り品 () 取扱い等 ()																					
走行 69,539マイル		シフト AT																											
外装色 パール		カラーNo. 0		エアコン		AG・AG・WAG ()		装備品のみ O印 を記入																					
()		内装色 ブラック		乗車定員 2人		PS		サンルーフ																					
左・右 左・右		ディーラー・並行		8,990円		エアロック		ABS ナビ TV キーレス																					
セールスポイント																													
TEIN車高調					修復歴 有・無																								
検査記入欄					<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																				
シートシワ					登録No. 月 日 までにも変更できる方																								
ドアミラーA					車体番号 LA400K-0012252																								
外装上面A多					シリアル No.																								
下廻りペイント					長さ cm																								
AWセンターキャップ欠					幅 cm																								
FW					高さ cm																								
内装					最大積載量 0 kg																								