

2015 Daihatsu Move 660 L		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LA150S	DISPLACEMENT 658 cc		
YEAR / REG. 2015/04	MILEAGE 113,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Kei		
CHASSIS NO. LA150S-0022167	DIMENSIONS (L X W X H) 340 × 148 × 163 cm		
SALES POINTS			
Back Camera		Navigation System	
INSPECTOR REPORT			
Seat scuffs, carpet stains, wheel scratches/damage, edge scratches, right center pillar paint damage, front cross member damage, underbody rust, front windshield stone chips, cloudy/dull left and right headlights, headliner stains/dirt, carpet wrinkles/scuffs/scratches, and other trim wrinkles/scuffs/scratches.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H27/4月	メーカー ダイハツ	ドア枚数 5	ボディ形状 軽四	評価点 3.5
車名 ムーヴ	グレード 660 L ナビ Bluetooth バックカメラ キーレス	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 660 cc	型式 DBA-LA150S	通称 型式	内装 A・B・C
車検 - - - / -	燃料 ガソリン	ディーゼル ハイブリッド ()	乗員運り品 (保証書・取扱説明書 等)	
走行 1万1千3百00km	シフト インパネ	CVT		
外装色 ブラックマイカM (X07)	カラーネー QD・AAG・WAG・ ()	エンジン QD・AAG・WAG・ ()	新車品のみ O印 を記入	
()	内装色	乗員定員 4 人	AW	サンルーフ
左・右 左・右	ディーラー	走行 8,780 km	エレクトロ AW	サンルーフ
セールスポイント ナビ、Bluetooth、Bカメラ、キーレス、第三者機関鑑定済		修復歴 有・O		
検査記入欄 シートすれ、カーペット汚れ、ホイール削れ・傷、エッジきず、右センターピラーペイント、Fクロスメンバー損傷、下廻り錆、フロントウィンドウ飛び石傷、左右ヘッドライト曇り・くすみ、天張りしめ・汚れ、カーペットしわ・すれ・きず、他トリムしわ・すれ・きず		A キズ B U ヘッドランプ C キズ・ヘッス D 色あせ・ボケ E ガラスキズ W 経年劣化 S サイズ C 両面 X 交換済 YX 交換済 名義中 月 日 までに名義できる方 車体 No. LA150S-0022167 長さ 高さ 幅 最大積載量 cm cm cm Kg		