

2015 Ford Explorer 5D XLT EcoBoost		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ABA-1FM5KH	DISPLACEMENT 2,260 cc		
YEAR / REG. 2015/11	MILEAGE 79,571 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Left		
EXTERIOR COLOR Other	BODY TYPE Other		
CHASSIS NO. 1FM5K7DH8GGA21510	DIMENSIONS (L X W X H) 505 × 200 × 180 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Cruise Control Side Camera		Roof Rails Leather Seats (Leather) Front Camera Back Camera	
INSPECTOR REPORT			
Seat wrinkles, some dirt and scratches in the interior, wheel scratches, scratches and dents.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		登録番号		シリアル番号		評価点		
H 27 11月		エクスプローラー		5D		グレート		
型式 ABA-1FM5KH		排気量 2,300 cc		駆動方式 2WD		4		
車種 R 08	年 11月	車況 自家用	シフト AT	変速機 AC	純正装備品 ○をつける			
走行距離 7万9千571 km	マイル 5万7千111	カラーNo. 色替無	内装色 不明	純正ナビ			純正TV	
外装色 約イットラファム	色替無	カラーNo. 不明	内装色 不明	純正ナビ			純正TV	
車台No. 1FM5K7DH8GGA21510	登録No. 千葉 303 ち 9677	リサイクル 21,610円	未納税	ナビ機能 (社外品含む) ○をつける			ナビ機能 (社外品含む) ○をつける	
定員 7人	積載量 505 kg	200 cm	180 cm	DVD再生可			CD	
輸入車のみ	モデル 年	輸入区分	タイプ	ハンドル	新車保証書			車検取得
ゼールスコメント								
注意事項・不具合箇所								
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入								
シートシワ								
ルーム内一部汚れキズ								
ホイールキズ								
キズ凹								
トリアロー								
キズ								
セビ								
フレ								
1点								
シャッキ								
無								