

2015 Honda N-BOX 660 Custom G L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-JF1	658 cc		
YEAR / REG.	MILEAGE		
2015/10	115,000 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF1-1660907	340 × 148 × 178 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Minor wear on interior and exterior, AC compressor faulty			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27/10月	メーカー ホンダ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4					
車名 N-BOX	グレード 660 カスタムGリパッケージ 社外ナビTV バックカメラ	駆動方式 2WD 4WD							
車種 自家用・その他 ()	排気量 660 cc	型式 DBA-JF1	通称 A・C	内装 A・C・C					
車検 - - 年 / 月	燃料 ガソリン	ディーゼル ()	後日送り品 (保証書・取扱説明書 等)						
走行 115,000 km	シフト インパネ	CVT							
外装色 ブラック	カラーNo. ()	エアコン ()	新車のみの O印 を記入						
内装色 ()	乗車定員 4 人	サンルーフ ()	車シート ()						
左・右 ()	輸入 ()	ディーラー ()	走行距離 9,790 km	エンジン ()					
セールスポイント									
★社外ナビTV★バックカメラ★電動スライドドア★リアシートスライド★スマートキー★スペアキー★リアシートスライド★プッシュスタートエンジン★HIDライト★フォグライト★ロールサンシェード★フロントアームレスト★リアアームレスト★チルトステアリング★シートリフター★フロアマット★サイドバイザー★									
検査記入欄									
内外装ウエスA									
ACコンプレッサ不具合									
修復歴 有 ()									
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	G	ガラスキズ
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
登録No.					名義中				
月					日				
JF1-1660907									
FW	トビ石	備A	ワレ	外装	小	ホイル	エアロ	シリアル	No.
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	車庫	最大積載量