

2015 Honda N-BOX CUSTOM SS Package		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-JF1	DISPLACEMENT 658 cc		
YEAR / REG. 2015	MILEAGE 79,271 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Kei		
CHASSIS NO. JF1-1526684	DIMENSIONS (L X W X H) 340 × 148 × 178 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
INSPECTOR REPORT			
No audio system, studless tires, left headlight stay cracked, rear spoiler paint fade, wheel scratches, front left side repaired, left front inner panel and front support BP distorted, left front pillar distorted.			

ORIGINAL JAPANESE AUCTION SHEET

H27 / 月		メーカー ホンダ		ドア枚数 5	ボディ形状 軽四	評価点 R																				
車名 N-BOXカスタム		グレード SSパッケージ		駆動方式 2WD																						
車種 自家用・その他 ()		排気量 660	型式 DBA-JF1	通称形式	内装 A・B																					
年	月	日	燃料 ガソリン	ディーゼル	後付部品 (保証書・取扱説明書 等)																					
走行 79,271 km		シフト AT																								
外装色 ブラック		カラーNo. NH850	エアコン AG・AG・WAG・ ()	装備品のみ ORP を記入																						
()		内装色	乗車定員 人	PS	AW	サンルーフ																				
左・右	左・右	ディーラー	走行	9,790円	エアバック	ABS																				
セールスポイント		両側パワースライドドア																								
検査記入欄																										
オーディオレス、スタッドレスT、左ヘッドライトステーフレ、RスポイラーPアセ、ホイールキズ、F左面修復T、左Fインパネ・FサポートBPヒズミ、左Fピラーヒズミ		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ割れ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・剥け</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	ヘコみ割れ	B	キズ・ヘコみ	P	色あせ・剥け	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ割れ	B	キズ・ヘコみ	P	色あせ・剥け	Q	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
登録No. 月 日		名義中																								
車体番号 JF1-1526684																										
FW	トピ石	傷A	フレ	外装	小	ホイール	エアロ																			
内装	シス	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	シリアルNo.																			
長さ		幅		高さ		最大積載量																				
cm		cm		cm		Kg																				