


2015 Honda N BOX N BOX 660 G L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-JF1	DISPLACEMENT 658 cc		
YEAR / REG. 2015/05	MILEAGE 8,746 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Kei		
CHASSIS NO. JF1-1628962	DIMENSIONS (L X W X H) 339 × 147 × 178 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Exterior has minor scratches and dents. Underbody has rust. Equipped with studless tires. Interior has dirt/stains, scratches, (D) stains, burn marks, holes, scuffs, tears, and rips. Front glass has scratches, stone chips, cracks, and repair marks, requiring replacement.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成27年 5月	車名・グレード N_BOX G-Lパッケージ	2WD 4WD	評価点 (4)		
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-JF1	排気量 660 CC	ドア 5 形状 CP		
定員 4人	積載 kg	外装 A	内装 C		
車種 自家用	シフト CAT	セールスポイント (正常に機能するものに限ります)			
車検 年 月 (日)	冷暖房 AAC	スマートキー・パワースライドドア(左側)			
走行 万 8千 746 km	燃料 ガソリン				
色 パール	色コード NH875P	装備品 (純正品に限り○をつけてください)			
R券 9,790 円		(PS) (PW) (BS) (TB) A W SR ナビ TV カフ			
注意事項申告欄		新車保証書 有・無			
外装 小A・小U					
下廻り サビ					
スタッドレスタイヤ					
室内 汚れ					
フロントガラス キズ・飛石・ヒビ割・リペア跡・X要	内装 キズ・破れ・コゲ・穴・スレ・キレ・破れ	A-キズ E-エケボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済			
車台番号 1628962		型式認定番号 17075	類別区分番号 0059		
登録番号		車検有効期限 339 日	長さ 147 cm		
			高さ 178 cm		