

2015 Honda Odyssey Odyssey 2.4 G Aero Package		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-RC1	DISPLACEMENT 2,356 cc		
YEAR / REG. 2015/01	MILEAGE 48,946 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Minivan		
CHASSIS NO. RC1-1100381	DIMENSIONS (L X W X H) 483 × 182 × 169 cm		
SALES POINTS			
Alloy Wheels Cruise Control Navigation System		Power Sliding Doors (Both Sides) (Drive... Back Camera	
INSPECTOR REPORT			
Exterior has minor scratches and dents. Aftermarket wheels and door mirrors have scratches. Seats show wear and sagging. Interior has dirt, scratches, burns, holes, wear, tears, and damage. Windshield has scratches, stone chips, cracks, and repair marks, requiring replacement.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成27年1月	車名・グレード オデッセイ G1700ハパッケージ	2WD 4WD	評価点 (4.5)
ディーラー・並行 型式 DBA-RC1	排気量 2400 CC	ドア 5 形状 木	定員 7人 積載 kg
モデル年式 年 ハンドル 左・右	シフト CAT	冷暖房 A/C	外装 B
車種 自家用	燃料 ガソリン	セーリングポイント (正常に機能するものに限り)	内装 B
車検 令和10年2月(日)	走行 4万8千946 km	スマートキー・社外アルミホイール・ETC パワースライドドア (両側) ナビ・TV・カメラ・プリップM	
色 ブラック	色コード NH731P/	諸備品 (純正品に限り○をつけてください)	
R券 14,420 円		(PS) (PW) (BS) (AB) (AW) SR ナビ TV カワ	
注意事項申告欄		新車保証書 有・無	
外装 小A・小U		後日品	
社外ホイール ワキズ		スタッドレスタイヤ	
ドアミラー キズ			
シートスレヘタリ			
ルーム汚損キズ			
フロントガラス キズ・飛石・ヒビ割・リペア跡・X要			
内装 キズ・汚レ・コゲ・穴・スレ・キレ・破レ			
車台番号 1100381			
登録番号 水戸 338 ち 8080			

車台番号 1100381
登録番号 水戸 338 ち 8080