

|                                                                                                                                                                                                        |                                              |                                              |               |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----------------------------------------------|---------------|
| 2015 SUBARU Impreza Sport 2.0i-S<br>EyeSight                                                                                                                                                           |                                              | OVERALL<br>4                                 |               |
|                                                                                                                                                                                                        |                                              | EXTERIOR<br>-                                | INTERIOR<br>- |
| MODEL CODE<br>GP7                                                                                                                                                                                      | DISPLACEMENT<br>1,995 cc                     |                                              |               |
| YEAR / REG.<br>2015/03                                                                                                                                                                                 | MILEAGE<br>73,473 km                         |                                              |               |
| DOORS<br>5                                                                                                                                                                                             | SEATS<br>5                                   |                                              |               |
| DRIVETRAIN<br>4WD                                                                                                                                                                                      | TRANSMISSION<br>AT                           |                                              |               |
| FUEL<br>Petrol                                                                                                                                                                                         | STEERING<br>Right                            |                                              |               |
| EXTERIOR COLOR<br>Pearl White                                                                                                                                                                          | BODY TYPE<br>Hatchback                       |                                              |               |
| CHASSIS NO.<br>GP7-090963                                                                                                                                                                              | DIMENSIONS (L X W X H)<br>442 × 174 × 147 cm |                                              |               |
| SALES POINTS                                                                                                                                                                                           |                                              |                                              |               |
| Alloy Wheels<br>Cruise Control                                                                                                                                                                         |                                              | Adaptive Cruise Control<br>Navigation System |               |
| INSPECTOR REPORT                                                                                                                                                                                       |                                              |                                              |               |
| Exterior: Significant scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains are partially present. Repair history: No abnormalities in the frame components. |                                              |                                              |               |

[illegible]