

2015 Jaguar XE XE S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-JA3VA	DISPLACEMENT 2,994 cc		
YEAR / REG. 2015/07	MILEAGE 89,300 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Sedan		
CHASSIS NO. SAJAB4AV5GA900284	DIMENSIONS (L X W X H) 468 × 185 × 142 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Pre-Collision Braking Back Camera Meridian (825W15SP)		Sunroof Leather Seats () Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Linear scratches on front bumper and right rear door. Ding on right rear door. Slight distortion on right front fender. Deteriorated window molding. Scuff marks on all wheels. For other minor scratches, please check the actual vehicle and the inspection report. Issues with the lower part of the sunshade when opening/closing. Worn button for sunroof sunshade. Scuffs on seats.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H27 7月	メーカー ジャガー	ドア数 4	ボディ形状 セダン	評価点 4
車名 XE	グレード XE S	駆動方式 4WD	車種区分 4WD	
車種 自家用・その他 ()	排気量 2990 cc	型式 CBA-JA3VA	登録区分 A・⑤・C	
年 10	月 6	日 89	時 300	分 00
走行 89,300	燃料 ガソリン	変速機 AT	後付選用品 (保証書・取扱説明書等)	
外装色 イタリアンレーシングレッド	カラーNo. 0	エアコン AG・AC・WAG・ ()	新車品のみ・O印を記入	
内装色 ブラック	乗車定員 5人	PS	ナビ	キーレス
左・前 22,640円	右・後 22,640円	ABS	TV	カーレス
セールスポイント				
【おすすめ装備】 ??メリディアンスピーカー ??サンルーフ ??シートヒーター ??バックカメラ ??電動パーキング				
検査記入欄				
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損				
名義中				
月 日 家でに名義せざる方				
SAJAB4AV5GA900284				
シリアルNo.				
車種				
最大積載量 0kg				