

2015 SUBARU Levorg 1.6 GT EyeSight Proud Edition		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE VM4	DISPLACEMENT 1,599 cc		
YEAR / REG. 2015/07	MILEAGE 70,862 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Station Wagon		
CHASSIS NO. VM4-055224	DIMENSIONS (L X W X H) 469 × 178 × 149 cm		
SALES POINTS			
Alloy Wheels		STI	
Adaptive Cruise Control		Cruise Control	
Navigation System			
INSPECTOR REPORT			
Core support distorted, Right front instrument panel distorted.			

新年度登録 H27 / 7月 メーカ スバル		ドア数 5 ボディ形状 ステーションワゴン		評価点 R																					
車種 自家用・その他 ()		排気量 1500 CC		型式 VM4																					
年表 - 年 - 月 - 日		燃料 ガソリン		ディーゼル ()																					
走行 70,862 km		シフト フロア AT		後日選り品 (保証書・取扱説明書 等)																					
外装色 アイスシルバーメタリック		カラーNo. 3B		新備品の品 O印 を記入																					
()		内装色 5		サンプル 車シート																					
シェン 左 ()		輸入区分 ディーラー		走行距離 13,610 km																					
セールスポイント																									
パワーステアリング/バックカメラ/TC/横滑り防止装置 (ESC) / 運転席エアバック/後部座席システム/スマートキー/キーレスエントリー/A B S / 助手席エアバック/サイドエアバック/メモリーナビゲーション/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/4WD/アイドリングストップ/ナビ/オートクルーズコントロール/DVD再生/ミュージックプレーヤー接続可		修復歴 0																							
検査記入欄		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/凹み</td><td>B</td><td>キズ/へこみ</td><td>P</td><td>色あせ/色むら</td><td>G</td><td>ガラスキズ</td></tr> <tr> <td>W</td><td>腐蝕跡</td><td>S</td><td>サビ</td><td>C</td><td>変色</td><td>X</td><td>交換品</td><td>XX</td><td>交換品</td></tr> </table>				A	キズ	U	へこみ/凹み	B	キズ/へこみ	P	色あせ/色むら	G	ガラスキズ	W	腐蝕跡	S	サビ	C	変色	X	交換品	XX	交換品
A	キズ	U	へこみ/凹み	B	キズ/へこみ	P	色あせ/色むら	G	ガラスキズ																
W	腐蝕跡	S	サビ	C	変色	X	交換品	XX	交換品																
コアサポート申込み 右フィンパネ申込み		登録地 千葉県																							
車体番号 VM4-055224		日 月 年																							
内装 ヨゴレ		外装 ヨゴレ																							