

2015 SUBARU Levorg 1.6GT-S EyeSight		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE VM4	DISPLACEMENT 1,599 cc		
YEAR / REG. 2015/02	MILEAGE 78,900 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Station Wagon		
CHASSIS NO. VM4-029928	DIMENSIONS (L X W X H) 469 × 178 × 149 cm		
SALES POINTS			
Alloy Wheels Leather Seats Cruise Control		STI Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Minor exterior scratches, shallow dents, fine scratches, touch-up paint spots, and left door mirror power folding malfunction.			

ORIGINAL JAPANESE AUCTION SHEET

型式番号 H27/2月	メーカー スバル	ドア数 5	ボディタイプ ステーションワゴン	評価点 4
車名 レヴォーグ	グレード 1.6GT-Sアイサイト	駆動方式 2WD	燃費区分 490	
車種 自家用・その他 ()	排気量 1600 cc	型式 VM4	通称 2WD	内装 A・B・C
年 -	月 -	日 -	燃料 ガソリン	ディーゼル
走行 78,900 km	インパネ	AT	登録年月日 (保証書・取扱説明書 等)	
外装色 ダークグレーメタリック	カラーNo. ()	エンジン 2.0L	装備品のみ O印 を記入	
5人	5人	5人	サンルーフ	ナビ
13,610円	13,610円	13,610円	ナビ	TV
セールスポイント				
★ステアロパーツ ★レザーシート ★ビルシュタインサスペンション ★運転席/助手席パワーシート ★運転席/助手席シートヒーター ★マートキー2個 ★LEDライト ★純正ナビ地デジTV ★ETC ★バックカメラ				
検査記入欄				
※外装小傷・薄凹み・薄縁傷有り ※タッチペン箇所有り ※左ドアミラー電格不良				
修理歴 有・無				
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損				
月 日 までに見学できる方				
VM4-029928				
内装 モビル シェ ヤブレ コガ コガス オーディオ スレ				