


2015 MAZDA Atenza Wagon 4WD XD L Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-GJ2AW	DISPLACEMENT 2,188 cc		
YEAR / REG. 2015/03	MILEAGE 96,700 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Station Wagon		
CHASSIS NO. GJ2AW-100714	DIMENSIONS (L X W X H) 481 × 184 × 148 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control		Leather Seats (Perforated Leather) Navigation System	
INSPECTOR REPORT			
Minor exterior scratches			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27/3月	メーカー マツダ	ドア枚数 5	ボディ形状 ステーションワゴン	評価点 4
車名 アテンザワゴン	グレード 4WD XD L パッケージ	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 2200	CC CC	型式 LDA-GJ2AW	通称 A・B・C
年 10	月 4	走行 96,700	燃料 ガソリン ハイブリッド ()	後付選り品 (保証書・取扱説明書等)
走行 96,700	マイル マイル	AT		
外装色 ジェットブラックマイカ	カラーNo. ()	エアコン A・AAG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5人	サンルーフ 有	シート 有	
左・前 左・前	ディーラー ディーラー	走行 走行	11,330円	エブリック エブリック
セールスポイント 純正ナビ/衝突安全装置/シートヒーター/車線逸脱防止支援システム/シートフルレザ/ヘッドランプLED/Bluetooth接続/TC/ABS/BD付ABS/横滑り防止装置				
検査記入欄 外装小傷有				
				
修復歴 有・無				
A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換品 XX 交換済				
登録No. 月 日 までにご査見できる方 名実中				
車体番号 GJ2AW-100714				
FW () 備A フレ 外装 小 ホイル エアロ シリアル No. A・曲 A・フレ				
内装 () シェ ヤブレ コダ コダス オーディオ スレ				
車重 cm 備 cm 高さ cm 最大積重量 Kg				