

2015 MAZDA Axela Sport XD		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-BM2FS	DISPLACEMENT 2,188 cc		
YEAR / REG. 2015/04	MILEAGE 24,595 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Hatchback		
CHASSIS NO. BM2FS-106721	DIMENSIONS (L X W X H) 446 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Leather Seats (Lux Suede, Leather)		Adaptive Cruise Control	
Navigation System		Bose Sound System (AUDIOPILOT2 + C...	
INSPECTOR REPORT			
Left side repair history. Minor damage on left step, left rear fender (partial), and left center pillar. Interior has some scratches and seat wrinkles.			

ORIGINAL JAPANESE AUCTION SHEET

型式番号 H27/4月	メーカー マツダ	ドア数 5	ボディタイプ コンパクト/ハッチバック	評価点 R
車名 アクセラスポーツXD	グレード LDA-BM2FS	駆動方式 2WD	4WD	
車種 乗用車・その他()	排気量 2200 cc	型式 LDA-BM2FS	通称 A・B・C	
年 -	月 -	日 -	燃料 ガソリン	燃料消費率 14.0 km/l
走行 24,595 km	シフト フロア	AT	後部座席 2人	
外装色 ワイン	カラーNo. (41V)	エアコン AG・AG・WAG・()	装備品のみ O印 を記入	
走行 10,770 km	ディーラー -	走行 10,770 km	ABS	エアバッグ
セールスポイント ハーフレザーシート、スマートキー、バックモニター、ヘッドアップディスプレイ	修復歴 G・無			
検査記入欄 左面修復歴、左ステップXX、左Rフェンダー一部XX、左センターピラーXX、ルーム内一部キズ、シートシワ	A キズ B ハッチオーバー C キズ・ヘリ D 色あせ・ボケ E ガラスキズ W 修復歴 S サビ C 腐食 X 交換部 XX 交換済			
	月 日 までに見学できる方			
	車検 BM2FS-106721			
内装 シロ	外装 シロ	ボディ シロ	エンジン シロ	最大積載量 kg