

2015 MAZDA Carol 5D GL		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-HB36S	DISPLACEMENT 658 cc		
YEAR / REG. 2015/06	MILEAGE 31,504 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Kei		
CHASSIS NO. HB36S-204601	DIMENSIONS (L X W X H) 339 × 147 × 147 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Minor scuffs on headliner, adhesive residue on dashboard, minor seat sagging, medium carpet tears, minor A-grade scratches on door trim and pillar trim, exterior paint fade, minor exterior scratches, minor bend on right rocker panel, minor A-grade scratches on rear bumper, and A-grade scratches on wheel covers.			

初年度登録番号	マツダ		ドア数	5	ボディ形状	軽四	評価点	4.5
H27 / 6月	車名	キャロル	グレード	GL 禁煙車 セーフティ 5人リッド STP		燃費 19.0 4WD		
車種	自家用・その他		排気量	560	型式	DBA-HB36S	国産	A ⑨ C
車検	- 年 / 月 / 日		燃料	ガソリン	ディーゼル	貴重品等 (保証書・取扱説明書等)		
走行	31,504 km		シフト	インパネ CVT				
外装色	カーラートン (26U)		エアコン	④b・AAG・WAG・()		新車のみのO印を記入		
初付	()		内装色	黒色		AW サンプル車		
左・右	ディーター		走行距離	4人		AW サンプル車		
購入区分	ディーター		走行距離	7,220円		TV		
セールスポイント								
☆バックギア時後付ソナー☆社外ナビ☆マニュアルエア コン☆アイドリングストップ☆運転席シートヒーター☆ キーレスキー								
検査記入欄 AIS検査員コメント ・天張りすれ<小>・ダツ板/側席・シートへたり<小>・カ ベツ外れ<中>・ドア内張りA<小>・ビラ内張A<小>・外 装パZ跡・外装小傷有、右前カミ曲がり<小>リアB'部A< 小>・新加加-A								
修正箇所 有・⑥								
検査項目 A 不正 U ヘッドライト B キズ・ヘコみ P 色あせ・汚れ G ガラスキズ W 経年劣化 S ゴキ C 腐食 X 交換部 XX 交換済 なにわ 59M る 7016 名表 月 日 所在地まで送る 車検番号 HB36S-204601								
内装 PW ドビ石 黒A フレ 外装 小 A・U ④b・曲 A・フレ 内装 正色 シシ ヤツレ コガ オーク・オス ④b 車検 339 車 147 車 147 最大積載量								