

2015 MAZDA CX-3 1.5 XD Touring Diesel Turbo		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-DK5FW	DISPLACEMENT 1,498 cc		
YEAR / REG. 2015/06	MILEAGE 46,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR White	BODY TYPE SUV		
CHASSIS NO. DK5FW-111693	DIMENSIONS (L X W X H) 428 × 177 × 155 cm		
SALES POINTS			
Alloy Wheels Navigation System		Adaptive Cruise Control Bose Sound System (7 speakers)	
INSPECTOR REPORT			
Front glass: Scratches, stone chips, cracks, repair marks, replacement required. Interior: Scratches, dirt, burns, holes, scuffs, tears, rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成27年 6月	車名・グレード CX-3 XD ツーリング	(2WD) 4WD	評価点 (4.5)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 LDA-DK5FW	排気量 1500 CC	ドア 5 形状 木
定員 5人	積載 kg	外装 B	内装 B

車歴 自家用	シフト FAT	セールスポイント (正常に機能するものに限ります)
車検 年 月 (日)	冷房 AAC	純正ナビ・Bluetooth・CD・DVD再生・バックカメラ
走行 4万5千850 km	燃料 軽油	BOSEサウンドシステム・ヘッドアップディスプレイ
色 グレー	色替 色コード 47A	ブラインドスポットモニター・LEDヘッドライト

R券 10,120 円	装備品 (純正品に限り○をつけてください)
注意事項申告欄	(PS) (PW) (BS) (AB) (AW)
外装 小A・小U	SR (4B) (TV) カワ
フロントガラス 内装	新車保証書 後日品
キズ・飛石・ヒビ割・リペア跡・X要	有・無
キズ・汚レ・コゲ・穴・スレ・キレ・破レ	

車台番号 111693	スベア
登録番号	

A-キズ E-エクボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済

型式指定番号	識別区分番号
車検有効期限	備考
備考	備考