

2015 MAZDA CX-3 XD Touring		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DK5FW	DISPLACEMENT 1,498 cc		
YEAR / REG. 2015/08	MILEAGE 75,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. DK5FW-115132	DIMENSIONS (L X W X H) 428 × 177 × 155 cm		
SALES POINTS			
Alloy Wheels Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Exterior has noticeable scratches and dents. Interior has some noticeable stains in parts. No frame damage.			

ORIGINAL JAPANESE AUCTION SHEET

青森内のカー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

型式年次登録 H27 8月	メーカー マツダ	ドア数 5	ボディ形状 SUV/クロカン	評価点 4
車種 C X-3	グレード XD ツーリング	登録年次 8月	排気量 1500	燃料 ディーゼル
車体色 セラミックメタリック	カラーNo. ()	リサイクル料 10,120円	車体番号 DK5FW-115132	重量 1500kg
年次 8年	月 8月	日 75,000	マイル 75,000	AC
シフト フロア 6 AT	駆動方式 5人	長さ 428cm	幅 177cm	高さ 155cm

車検返却日
(保証書・取説説明書等)

装備
CD/DVDプレイヤー、ナビゲーションシステム、Bluetooth、バックカメラ、ABS、ESP、VDC、HAC、BSM、LCA、MRCC、ACC、ETC、スマートキー、パワーステアリング、パワースhift、パワーステアリング、パワースhift、パワーステアリング、パワースhift

セーリングポイント
CD/DVDプレイヤー、ナビゲーションシステム、Bluetooth、バックカメラ、ABS、ESP、VDC、HAC、BSM、LCA、MRCC、ACC、ETC、スマートキー、パワーステアリング、パワースhift、パワーステアリング、パワースhift

査定員記入欄

※ダメージレベルに関する注意事項
ダメージレベルは、車体の損傷状況を表す指標です。ダメージレベルが大きいほど、車体の損傷が大きいことを示します。ダメージレベルは、車体の損傷状況を表す指標です。ダメージレベルが大きいほど、車体の損傷が大きいことを示します。

クオリティグレード説明
外装: 気になるようなキズやヘコミがあります。
内装: 気になる汚れ等が、部分的にあります。
修復歴: 骨格部位に異常はありません。

車体状況の図解
小: カードサイズ未満
中: A4サイズ未満
大: A4サイズ以上
その他: 不明

車体状況の図解
小: カードサイズ未満
中: A4サイズ未満
大: A4サイズ以上
その他: 不明