


2015 Mazda CX-3 XD Touring		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-DK5FW	DISPLACEMENT 1,498 cc		
YEAR / REG. 2015/08	MILEAGE 25,200 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE SUV		
CHASSIS NO. DK5FW-116297	DIMENSIONS (L X W X H) 428 × 177 × 155 cm		
SALES POINTS			
Alloy Wheels Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Front windshield stone chip, interior dirt/stain			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27/8月	メーカー マツダ	ドア枚数 5	ボディ形状 SUV/クワカン	評価点 4.5
車名 CX-3	グレード XDツーリング	駆動区分 2WD 4WD		
車歴 自用・その他 ()	排気量 1500 cc	型式 LDA-DK5FW	通称 形式	内装 A・⑥・C
車検 8年8月/抹消	燃料 ガソリン	デジ ハイブリッド ()	後日選り品 (保証書・取扱説明書 等)	
走行 25,200 km	シフト AT			
外装色 クリスタルホワイトパールマイカ	カラーNo. ④D・AAG・WAG・ ()	装備品のみ O印 を記入		
内装色 ()	乗車定員 5人	④P	④A	サンルーフ
④L 左・前 ④R 右・後 ④M 中	ディーラー ・	走行 10,120 km	④E エレクト ④S ステア ④T ト ④V V	④S ス
セールスポイント 純正ナビ/衝突安全装置/車線逸脱防止支援システム/シートハーフレザー/ハグ'ラング LED/USBジャック/Bluetooth接続/E BD付ABS/横滑り防止装置/アイドリングストップ				
検査記入欄		修復歴 有・⑤		
		A ボディ U ヘコ B キズ P 色あせ Q ガラス W 修理 S サビ C 腐食 X 交換 XX 交換 名 査 中 月 日 まで に 名 査 で 可 車 体 番 号 DK5FW-116297		
④P 内装	④A シス	④L ヤブレ	④R コグ	④M コグ穴
④D オイル	④E 曲	④S A・フレ	④T エアロ	④V シリアル
④W 長さ	④X 幅	④XX 高さ	④V 最大積載量	kg