


2015 Mazda Demio 13S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-DJ3FS		DISPLACEMENT 1,298 cc	
YEAR / REG. 2015/11		MILEAGE 27,094 km	
DOORS 5		SEATS 5	
DRIVETRAIN 2WD (FF)		TRANSMISSION AT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR Purple		BODY TYPE Hatchback	
CHASSIS NO. DJ3FS-138614		DIMENSIONS (L X W X H) 406 × 170 × 150 cm	
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Driver's mirror: minor scratch. Pet hair in interior.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27/11月		メーカー マツダ		ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4																				
車名 デミオ		グレード 13S		駆動区分 2WD 4WD																						
車種 自家用・その他 ()	排気量 1290 cc	型式 DBA-DJ3FS	通称 型式	内装 A・B・C																						
車検 - - 年 / 月	燃料 ガソリン	ディーゼル ハイブリッド ()	後付選り品 (保証書・取扱説明書 等)																							
走行 27,094 km	シフト AT	ナビSD、スベアキー																								
外装色 パープル	カラーNo. (44R)	エアコン AG・QG・WAG・()	新着品のみ O印 を記入																							
()	内装色	乗車定員 5 人	PS	PS	AW	サンルーフ																				
ハンド 区分	ディーラー 並行	リサイクル料 9,130 円	エコパック	ABS	ESP	キーレス																				
セールスポイント ESC、BS、AEB、PUSHSTART、スマートシティブ レーキサポート																										
検査記入欄 Dミラー A、室内動物毛			修復歴 有・無																							
			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ・へこみ</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換歴</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	へこみ/サレ	B	キズ・へこみ	P	色あせ・汚れ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ・へこみ	P	色あせ・汚れ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換済																	
			登録No. 名義中																							
			月 日 までに名義できる方																							
			車検番号 DJ3FS-138614																							
FW	トビ	ワレ	外装	小	ホイール	エアロ	シリアル No.																			
内装	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	取付	長さ cm																			
						高さ cm	最大積重量 kg																			