

2015 MAZDA Demio 15XD Touring		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-DJ5FS	DISPLACEMENT 1,498 cc		
YEAR / REG. 2015/07	MILEAGE 39,307 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Other		
CHASSIS NO. DJ5FS-135137	DIMENSIONS (L X W X H) 406 × 169 × 150 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Light line scratches on exterior, interior dirt and trim scratches, dashboard adhesive residue, scuffs on shift knob and steering wheel, seat sagging, bumper bottom, mirror A			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式番号	17817	納税証明書番号	0002	シリアル番号		評価点	4
年	月	日	車名	グレード	駆動				
H 27	7		デミオ	15XD ケーリング	4WD				
型式	LDA-DJ5FS	排気量	1,500 cc	燃料	ガソリン				
車検	年	月	車種	自家用	シフト	6MT	冷房	AC	純正装備品 ○をつける
走行距離	3	9	千	307	km	マイル	5	純正ナビ	純正TV
外装色	スノーフレイクホワイトパール	色	色替無	カラーNo.	内装色	純正AW	エアB	SR	TV増設 (社外品含む) ○をつける
車台No.	DJ5FS-135137	名義	期限	月	日	フルセグ	ワンセグ	アナログ	ナビ増設 (社外品含む) ○をつける
登録No.	抹消	リサイクル	9,130円	未納税	HDD	DVD	SD		
定員	5人	重量	kg	406	cm	DVD再生可	CD		
輸入車のみ	モデル	年式	輸入区分	ディーラー	登録	ハンドル	左	新車保証書	車検取説
セールスポイント									
注意事項・不具合箇所									
検査員記入欄：修理歴「有」の場合は修理箇所・交換箇所を記入									
外装薄い線キズ									
室内汚れ、内張傷									
ダッシュ版のり付									
シフトノブ・ハンドルすれ									
シートへたり									
バンパー下・ミラーA									
ドアミラー	キズ	ヒビ	ウレ						
エッジ	無	ジャッキ	無						

