

2015 MercedesBenz BenzCLAShootingBrake Mercedes-Benz CLA 1.6 CLA180 Shooting Brake Sport		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-117942	DISPLACEMENT 1,595 cc		
YEAR / REG. 2015/11	MILEAGE 30,610 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Other		
CHASSIS NO. WDD1179422N292074	DIMENSIONS (L X W X H) 468 × 178 × 143 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Cruise Control Navigation System		Power Tailgate Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Front glass: Scratches, stone chips, cracks, repair marks, replacement/major repair needed. Interior: Scratches, dirt, burns, holes, scuffs, tears, rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成27年11月	車名・グレード ベンツCLAシューティングブレーク CLA180シューティングブレークスポーツ	2WD 4WD (4)	評価点 (4)
ディーラー・並行 モデル年式 DBA-117942	型式 1600 CC	ドア 5 形状 木	定員 5人 積載 kg
外装 ホワイ	内装 B	外装 B	内装 B
車種 自家用	シフト CAT	セールスポイント (正常に機能するものに限ります)	
車検 令和8年11月(日)	冷暖 AAC	スマートキー・ETC・HIDヘッドライト	
走行 3万0千610km	燃料 ガソリン	ナビ・バックカメラ・ETC・HID	
色 ホワイト	色コード マイ	装備品 (純正品に限り○をつけてください)	
R券 19,390円		(PS) (PW) (BS) (AB) (AW) SR ナビ TV カワ	
注意事項申告欄		新車保証書 有・無	
外装 小A・小U 外装 うすい傷キズ 外装 T/Pアト 外装 年式相応 右サイドエアロキズ ホイール キズ トリムシワスレキズ シートシワスレ		T スベア	
フロントガラス キズ・汚れ・ヒビ割・リペア跡・X要 内装 キズ・汚れ・コゲ・穴・スレ・キレ・破れ		A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
車台番号 2N292074	登録番号 市川 310 ゆ 1211	型式 18127	識別区分番号 0112
		長さ 468cm	幅 178cm
			高さ 143cm