


2015 MITSUBISHI Delica D2 S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
MB15S	1,242 cc		
YEAR / REG.	MILEAGE		
2015/03	64,921 km		
DOORS	SEATS		
5	5		
TRANSMISSION	FUEL		
AT	Petrol		
STEERING	EXTERIOR COLOR		
Right	Pearl White		
BODY TYPE			
Minivan			
CHASSIS NO.	DIMENSIONS (L X W X H)		
MB15S-255930	371 × 162 × 177 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
INSPECTOR REPORT			
Light interior dirt, seat edge scuffs, wheel and door mirror scratches			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H27/3月	メーカー 三菱	ドア枚数 5	ボディ構造 ミニバン/ワンボックス	評価点 4					
車名 デリカD:2S	グレード S	駆動区分 2WD 4WD							
車種 自家用・その他 ()	排気量 1200 cc	型式 MB15S	通称 型式	内装 A・⑨・C					
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日送付品 (保証書・取扱説明書 等)						
走行 64,921 km	シフト フロア	AT							
外装色 パールホワイト	カラーNo. ()	エアコン AG・QG・WAG・()	新着品のみ O印 を記入						
内装色 ()	乗車定員 5 人	PS	サンルーフ	革シート					
ハンド 左・右	輸入 区分	ディーラー ・ 並行	ナビ	TV					
11,180円		預託金	エアロック	AS					
セールスポイント フルフラットTC/横滑り防止装置 (ESC)/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/両側電動スライドドア/社外ナビ/ドラレコ前後ミラー型バックカメラ									
検査記入欄 ルーム内薄汚れ シートフチスレ ホイール・ドアミラーキズ									
									
修復歴 有・⑨									
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ
W	補修跡	S	サビ	C	腐食	X	交換歴	XX	交換済
登録No.					名義中				
月					日 までに名義できる方				
車体番号 MB15S-255930									
FW	⑨	備A	ワレ	外装	小	ホイール	エアロ	シリアル No.	
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	長さ cm	幅 cm
								高さ cm	最大積重量 kg