

2015 MITSUBISHI Delica D5 Delica D:5 2.2 D Power Package 4WD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-CV1W	DISPLACEMENT 2,267 cc		
YEAR / REG. 2015/10	MILEAGE 48,053 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Minivan		
CHASSIS NO. CV1W-1010208	DIMENSIONS (L X W X H) 473 × 179 × 187 cm		
SALES POINTS			
Alloy Wheels Cruise Control Navigation System		Power Sliding Doors (Both Sides) (Both... Back Camera	
INSPECTOR REPORT			
Wheel scratches, door mirror scratches, minor exterior scratches (A) and dents (U), rear reinforcement dent, interior trim scratches, interior dirt, interior trim scuffs, seat dirt. Front glass has scratches, stone chips, cracks, and repair marks, requiring replacement. Interior has scratches, dirt, burns, holes, scuffs, tears, and rips.			

初度登録年月 平成 27 年 10 月	車名・グレード テリカD5 Dハワーパッケージ	2WD 4WD	評価点 (4)
ディーラー・並行 モデル年式 年 ハンドル 左・右	型式 LDA-CV1W	排気量 2200 CC	ドア 5 形状 箱型 定員 7人 積載 kg
車種 自家用		シフト CAT	
車検 年 月 (日)		冷房 AAC	
走行 4万8千 053 km		燃料 軽油	
色 パール	色替 W23A19		
R券 14,710 円			
注意事項申告欄 ホイル キズ ドアミラー キズ 外装 小A・小U Rホースメント蓋み 内張り キズ 室内 汚れ 内張り すれ シート 汚れ			
フロントガラス 内装 キズ・傷 ヒビ割 リベア跡・X要 (キズ・傷)・コゲ・穴・変色 キレ・破れ			
車台番号 1010208			
登録番号 473 179 0001			

A:キズ E:エグボ U:凹み W:横傷跡 S:サビ C:腐食 XX:交換済
 型式動機番号 473 179 0001
 車検証印字 473 179 0001