

2015 MITSUBISHI ek Wagon M		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE B11W	DISPLACEMENT 659 cc		
YEAR / REG. 2015/07	MILEAGE 68,316 km		
DOORS 5	SEATS 4		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Kei		
CHASSIS NO. B11W-0129612	DIMENSIONS (L X W X H) 340 × 148 × 162 cm		
INSPECTOR REPORT			
Front glass stone chip, interior scuffs and dirt, lower support (screw) distortion, core support deformation, condenser pushed in, many dents on roof, and various paint repairs. Front glass has scratches, stone chips, cracks, repair marks, and requires replacement. Interior has scratches, dirt, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成27年 7月	車名・グレード eKワゴン M 4WD	2WD 4WD	評価点 (3.5)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-B11W	排気量 660 CC	ドア 5 形状 積載 kg
		定員 4人	外装 内装 B C
車歴 自家用	シフト CVT	セールスポイント (正常に機能するものに限りです)	
車検 年 月 (日)	冷房 AC	キーレス	
走行 6万8千316 km	燃料 ガソリン		
色 シルバー	色替 色コード A31	装備品 (純正品に限り○をつけてください)	
R券 8,060 円		PS PW ABS ABS AW SR ナビ TV カワ	
注意事項申告欄		新車保証書 後日品 有・無	
Fガラス飛石			
内装傷スレ汚れ			
ロアサポート (ねじ) 歪			
コアサポート歪			
コンデンサー押され			
ルーフえくぼ多			
各AU			
フロントガラス 内装	キズ・飛石・ヒビ割・リペア跡・X要 キズ・汚レ・コゲ・穴・スレ・キレ・破レ	A-キズ E-エクボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
車台番号 0129612		型式指定番号 参考	
登録番号		車庫証明用 参考	